

ਵੱਲ.

ਸਿਰਜਪਲ,

ਭਾਈ ਬਹਿਲੋ ਪਬਲਿਕ ਸਕੂਲ,


ਫਫਤੇ ਭਾਈਕੇ, ਜਿਲ੍ਹਾ ਮਾਨਸਾ।

ਵਿਸ਼ਾ:- ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ। (ਸਾਲ 2021-22)

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰ. BBPS/SGPC/2021/2924 ਮਿਤੀ 14/12/2021

ਤੁਹਾਡੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਇੰਜੀਨੀਅਰ ਇੰਚਾਰਜ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ। ਨਿਰੀਖਣ ਦੌਰਾਨ ਪਾਇਆ ਗਿਆ ਕਿ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ 31/03/2022 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।


ਨੱਥੀ/ ਕੇਸ ਫਾਈਲ।



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।

ਪਿੱਠ ਅੰਕਣ ਨੰ.

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਉਪ ਮੰਡਲ ਨੰ. 1, ਮਾਨਸਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਪੱਤਰ ਨੰ. 629 ਮਿਤੀ 12/01/2022 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।


ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,
ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ,
ਮਾਨਸਾ।


Principal
Bhai Behlo Public School
Phaphre Bhaike (Mansa)
Affiliation No. : 1631216
School Code : 21207

Building Safety Report


NAME OF SCHOOL: Bhai Behlo Public School, Phaphre Bhaike (Mansa)


(District- MANSĀ)


As per report of 11.1.2022 Assistant/Junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions.

1. The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available
2. In case any addition, alteration, expansion and modification to this building are required to be done, regarding this inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. Immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building 21757-57 sq which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2021-2022

As per visually inspection as reported by the concerned Assistant/Junior Engineer the above building may be used for normal use for one year up to 31-3-2022 subject to the above conditions.


Assistant/Junior Engineer.


Sub Divisional Engineer,
Provl. Sub Divn. No.1 PWD (B&R)
Mansa


Principal Jwinder Singh
Bhai Behlo Public School
Phaphre Bhaike (Mansa)
Affiliation No. : 1631216
School Code : 21207

Scanned with CamScanner

Scanned with CamScanner